DEVELOPMENT BANK OF THE PHILIPPINES

SCOPE OF WORKS

REPAIR WORKS FOR STA. CRUZ BRANCH

I. APPROVED BUDGET FOR THE CONTRACT

PESOS: THREE HUNDRED FORTY-SIX THOUSAND FIVE HUNDRED AND 53/100 (346,500.53) INCLUSIVE OF ALL APPLICABLE TAXES

| Description | (** Quantity | Amount | | |
|--|--------------|--------------|--|--|
| Repair of Branch Ceiling and Comfort Rooms | 1 lot | ₱ 346,500.53 | | |

II. REQUIREMENTS

1. Scope of Services

Complete repair of **DBP Sta. Cruz (Davao) Branch** ceiling (interior and exterior) and comfort rooms, including general cleaning and hauling of debris.

| Exteri | or | Cai | ilina |
|--------|----|-----|-------|
| | U | CE | ши |

Fiber Cement Board

4.5mm thick fiber cement boards, properly

fastened to furring channels using corrosionresistant self-tapping screws at the

recommended spacing

Interior Ceiling

Gypsum board

12.5mm thick moisture resistant gypsum

board screw attached on 2" GI double furring

channel spaced 0.60m on center

Acoustic board

600mm x 600mm x 10mm thickness acoustic board ceiling on tee runners (main tee, cross tee, wall angle) complete with clips and threaded hanger rods at every 0.60m both

ways

Ceiling Finishes

Gypsum board
 Fiber Cement board

acrylic/latex, flat finish, color. white acrylic/latex, flat finish, color. white

Comfort Rooms (Toilet Fixtures and Accessories)

Above-counter faucet

stainless, lever handle, standard spout

Soap dispenser

wall-mounted, push-button type

Water closet

tank type, lever type (including other

accessories)

Hygienic spray/bidet

stainless steel finish (1m long)

| | Conforme: |
|------|--|
| | Bidder's Company Name |
| Name | & Signature of Authorized Representative |
| | Designation |
| | Date |

REPAIR WORKS FOR STA, CRUZ BRANCH

2. Other Requirements

- a. Supplier shall carefully dismantle the damaged ceiling, including framing members, without affecting adjacent structures.
- b. Supplier shall submit a phasing plan subject for DBP's approval.
- c. Supplier shall remove one (1) unit cassette-type air conditioning unit near the Branch Head area, including refrigerant piping, drain line, and electrical connections.
- d. Supplier shall temporarily remove and reinstall the existing lighting fixtures and security/fire protection devices (if any) mounted on the ceiling.
- e. Supplier shall test all lighting fixtures and devices to ensure proper functionality after reinstallation.
- f. Supplier shall install hanger rods anchored to the roof framing at 0.60m spacing both ways, complete with suspension clips and accessories.
- g. Supplier shall ensure all installed plumbing fixtures undergo leak and flood test.
- h. All items must conform with the standards implemented by the Bureau of Philippine Standards of the Department of Trade and Industry (DTI-BPS).

III. CONDITIONS OF THE CONTRACT

- The supplier shall ensure that the items delivered are in accordance with the specifications required by the DBP. DBP has the right to reject delivery if item/s delivered were found to be defective and not according to the required specifications/model.
- Upon completion of works, the supplier shall remove all temporary structures and surplus materials before leaving the premises. All old materials removed from the site shall be carefully piled up.
- 3. The supplier shall be fully responsible for the safety of his men and clearly understands and agree that no employer-employee relationship shall exist between the contractor's men and the DBP. Any damage caused by the supplier or his men to any property of the DBP or injury or death to a third party shall be the sole responsibility of the Supplier and the latter shall pay the cost or shoulder the burden thereof.
- 4. The DBP may terminate/cancel the Purchase Order (PO)/Notice to Proceed (NTP) should the supplier fail to deliver, perform and comply with its obligation.
- 5. **Delivery Period:** The supplier shall complete all works within **forty-five (45) calendar** days after receipt of PO/NTP.
- 6. **Point of Delivery:** DBP Sta. Cruz Branch, Sta. Cruz Public Market, National Highway Sta. Cruz, Davao del Sur
- 7. The supplier to submit a detailed estimate (see attached blank BOQ).
- 8. The supplier to submit Performance Security (see attached)

| | Conforme: |
|-------------|-------------------------------------|
| | Bidder's Company Name |
| Name & Sign | nature of Authorized Representative |
| | Designation |
| | Date |

REPAIR WORKS FOR STA. CRUZ BRANCH

IV. PAYMENT

- 1. One-time, full payment shall be issued upon completion/acceptance of all works.
- 2. When the supplier fails to satisfactorily complete all works under the contract within the specified delivery schedule, inclusive of duly granted time extensions, if any, the supplier shall be liable for damages-in an amount equal to one-tenth (1/10) of one percent (1%) of the cost of the delayed goods scheduled for delivery for every day of delay until such goods are finally delivered and accepted by DBP following the provisions stipulated in RA 12009.

V. WARRANTY

In order to assure that manufacturing defects shall be corrected by the supplier, a warranty shall be required from the contract awardee for a minimum period of **one (1)** year after completion/acceptance by the procuring entity of the delivered items

Recommended by:

ENGR. JASON G ABALAJEN

Concurrent CFMD-WEU

(per Department Order No. 2025-117 dated 09 October 2025)

Approved by:

SIGNED

ENGR. JOSE FRANCISCO E. PEREZ

SM-OIC, CFMD

(per Group Order No. 3459 dated 06 October 2025)

Conforme:

Bidder's Company Name

Name & Signature of Authorized Representative

Designation

Date

REPAIR WORKS FOR STA. CRUZ BRANCH

Project Name

STA. CRUZ PUBLIC MARKET, NATIONAL HIGHWAY STA. CRUZ, DAVAO DEL SUR

Project Location

| ITEM | DESCRIPTION | QTY | UNIT | ESTIMATED DIRECT COST LABOR & MATL'S | MARK-UP | | TOTAL MARK-UP | | | TOTAL INDIRECT | | |
|------|--|--------|-------|--------------------------------------|----------|---|---------------|-----------|----------|----------------|------------|-----------|
| | | | | | OCM | PROFIT | % | VALUE | VAT | COST | TOTAL COST | UNIT COST |
| 1 | GENERAL REQUIREMENTS | | | i i | i | | | | | | | |
| 1.1 | Mobilization/demobilization | 1.00 | lot | 5,000.00 | * 1 | | 0% | 0,00 | 250,00 | 250.00 | 5,250.00 | 5,250,00 |
| 1.2 | Health and safety | 1.00 | lot | 7,500.00 | | 750.00 | 10% | 750.00 | 412.50 | 1,162.50 | 8,662.50 | 8,662.50 |
| | Temporery scaffoldings and platforms | 1,00 | lat | 12,000.00 | 1,800.00 | 1,200.00 | 25% | 3,000.00 | 750.00 | 3,750.00 | 15,750.00 | 15,750.00 |
| 1.4 | Temporary Utilities (power/water) | 1.00 | lot | 5,000.00 | 750.00 | 500.00 | 25% | 1,250.00 | 312,50 | 1,562.50 | 6,562.50 | 6,562.50 |
| | | | | | | | | | | sub-total | 38,225.00 | |
| _ | SITE WORKS | | | | | | | | | 31 | | |
| 2.1 | Dismarting/Replacement of damaged gypsum board ceiling, including the removal of one (1) unit cassette type air conditioner Location: Banking Hall and Branch Head area | 1.00 | lot | 10,500.00 | 1,575.00 | 1,050,00 | 25% | 2,625.00 | 656.25 | 3,281.25 | 13,781.25 | 13,781.25 |
| 2.2 | Temporary removal and reinstallation of ceiling mounted utilifies, inlouding lighting fixtures, security/fire protection devices (if any) Location: Banking Hall, Branch Head area Back Office, Pantry and Storage Room | 1.00 | lot | 14,000,00 | 2,100.00 | 1,400.00 | 25% | 3,500.00 | 875.00 | 4,375.00 | 18,375.00 | 18,375.00 |
| 2.3 | General cleaning and Hauling of debris | 1.00 | lot | 5,000.00 | 750.00 | 500.00 | 25% | 1,250,00 | 312.50 | 1,562.50 | 6,562.50 | 0,582.50 |
| | | | | | | | | | | sub-total | 38,718.75 | |
| 3 | FINISHES | | | | | | | | | | | |
| 3.1 | Ceiling Finishes | | | | | | | | | | İ | |
| | 3.1.1 CF-1: 12mm thk. Gypsum board on furring channel on carrying channel complete with dips and hanger rods at every 0.0m both ways Location: Barking Hall, Branch Head area, and Exterior Celling (Front and Side) | 47.26 | m.ps | 40,171.00 | 6,025.66 | 4,017.10 | 25% | 10,042.75 | 2,510.69 | 12,553.44 | 52,724.44 | 1,115.63 |
| | 3.1.2 CF-2: 4.5mm thk. Fiber cement board on furring channel on carrying channel complete with clips and hanger rods at every 0.60m both ways Location: Exterior Celling (Front and Side) | 58.52 | m.ps | 49,742.00 | 7,481,30 | 4,974.20 | 25% | 12,435.50 | 3,108.86 | 15,544,38 | 65,286.38 | 1,115.63 |
| | 3.1.3 CF-3: Replacement of 600mm x 600mm x 10mm this acoustic board ceiling on tee runners (main tee, cross tee, wall angle) complete with dips and threaded hanger rods at every 0,60m both ways Location: Back Office, Partry and Storage Room | 41.10 | sq.m | 34,935.00 | 5,240.25 | 3,493.50 | 25% | 8,733.75 | 2,183.44 | 10,917.19 | 45,852.19 | 1,115.63 |
| 3.2 | Painting works | | | | | _ | | | | | | |
| | 32.1 Exterior Ceiling | | | | 1 | | | | | | | |
| | 32.1.2 PW-E: Ficemboard ceiling: acryfic/latex, flat finish, color: white | 64.32 | sq.m | 13.507.20 | 2.026.08 | 1.350.72 | 25% | 3.376.80 | 844.20 | 4.221.00 | 17.728.20 | 275.63 |
| | 3.2.2 Interior Ceiling | | | | 1 | .,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | | | | 1 | 11112020 | 2,10,00 |
| | 32.2.1 PW-I: All gypsum ceiling: acrylic/latex, flat finish, color: white | 101.95 | sg.m | 21,409,50 | 3,211,43 | 2.140.95 | 25% | 5.352.38 | 1.338.09 | 6,890,47 | 28.099.97 | 275.63 |
| | | | | 4 | | | | | | sub-total | 209,891.18 | |
| 4 | PLUMBING WORKS | | | | | | | | | | | |
| 4.1 | Toilet Fixtures and Accessories | | | | | | | | | | | |
| | 4.1.1 Above-counter faucet (stainless, lever handle, standard spout) | 2.00 | set/s | 2,500.00 | 375.00 | 250.00 | 25% | 625.00 | 156.25 | 781.25 | 3,281.25 | 1,640,63 |
| | 4.1.2 Soap dispenser (wall-mounted, push-button type) | 2.00 | set/s | 1,700.00 | 255.00 | 170.00 | 25% | 425.00 | 106.25 | 531.25 | 2,231.25 | 1,115,63 |
| | 4.1.3 Water closet (tank type, lever type) including other accessories | 2,00 | set/s | 15,600,00 | 2,340.00 | 1,580.00 | 25% | 3,900.00 | 975.00 | 4,875.00 | 20,475.00 | 10,237.5 |
| | 4.1.4 Hygienic spray / bidet (stainless steel finish) | 2,00 | set/s | 1,882.00 | 282.30 | 188.20 | 25% | 470.50 | 117.63 | 588.13 | 2,470.13 | 1,235.0 |
| 4.2 | Other item of work necessary to complete the intent of the plan and specs (specify): | | | | | | | | | | | |
| | - Consumables (tape, sealant, fittings, etc) | 1.00 | lot | 2,143.00 | - 3 | 214.30 | 10% | 214.30 | 117.87 | 332.17 | 2,475,17 | 2,475.1 |
| | | | | | | | | | | sub-total | 30,932.80 | |
| | | | | 7.37 | | | | | | TOTAL COST | 346,500,53 | - |

Propared by: SIGNED

ENGR. ADRIEUDOH G. BAUTISTA Property & Facilities Specialist

Reviewed by:

SIGNED

ENGR. JUSTIN TROYIC. PAGWAGAN Senior Procest & Pacifities Specialist

ENGR, JASON GABALAJEN
Concurred DIC WEU
(per Department Order No. 2025-117 dtd 10/09/2025)

Approved by:

SIGNED

ENGR. PERÉZ SM-OIC, (per Group Order No. 3459 dtd 10/06/2025)


Conforme:

Bidder's Company Name

Name & Signature of Authorized Representative

Designation

Date



vic PF

